



<i>Signal (P2)</i>				
<i>Pin</i>	<b>Color</b>	<b>Function</b>	<b>Direction</b>	<b>Volt</b>
<i>1</i>		USB +	IN	-
<i>2</i>	Orange/White	Serial In	IN	+/- 5
<i>3</i>	Blue	Flash OUT	OUT	+/- 5
<i>4</i>	Brown & Brown/White	+ 12 Volts	IN	0-14
<i>5</i>	Blue/White	Flash IN	IN	+/- 5
<i>6</i>	Green/White	Serial Out	OUT	+/- 5
<i>7</i>		USB -	IN	
<i>8</i>	Orange & Green	GROUND	IN	-



<i>Signal (P2)</i>				
<i>Pin</i>	<b>Color</b>	<b>Function</b>	<b>Direction</b>	<b>Volt</b>
<i>1</i>	Green/White	W TANK 1	IN	0
<i>2</i>	Green	W TANK 2	IN	-
<i>3</i>	Orange & Orange/White	FUEL	IN	0-3.3
<i>4</i>	Blue	TEMP	IN	0-3.3
<i>5</i>	Blue/White	OIL	IN	12-14
<i>6</i>	Brown & Brown/White	GROUND	IN	3.3